

## Interference

## MXL2, MXG and MXS power noise related to the “crank”

---

**Problem**

Dash locks at the “crank”.

**Note**

This problem may appear on the following systems:

- **MXL2:** up to SN 4302188
- **MXS:** up to SN 450087
- **MXG:** up to SN 4201217

**Solution**

Use the external power **filter** EOF-01 part number: **X08EPF000**

