



Data Key Release history

Version	Date	Change/additions
33.50	Feb 18th 2014	<ul style="list-style-type: none">■ Fixed the issue that sometimes didn't allow to download the memorized data from MyChron4
33.46	Sep 6th 2013	<ul style="list-style-type: none">■ Fixed bug in Download function that introduced a delay to the start of this procedure
33.44	Sep 3rd 2013	<ul style="list-style-type: none">■ Added management of SmartyCam HD
33.42	Jul 24th 2012	<ul style="list-style-type: none">■ Fixed bug in Firmup function that didn't work correctly in "no force update" mode
33.40	Sep 13th 2010	<ul style="list-style-type: none">■ Improved firmup management■ Added GPS maps saving in firmup management
33.37	Jul 30th 2010	<ul style="list-style-type: none">■ Added Upgrade for MyChron Expansion
33.34	Jun 3rd 2010	<ul style="list-style-type: none">■ Added Management of MyChron Expansion
33.33	Mar 5th 2010	<ul style="list-style-type: none">■ Fixed bug on upgrade Firmware GPS with SmartyCam connected
33.32	Feb 23th 2010	<ul style="list-style-type: none">■ Management of GPS05
33.31	Nov 24th 2009	<ul style="list-style-type: none">■ Management GPS04
33.30	Apr 28th 2009	<ul style="list-style-type: none">■ Added management of SmartyCam
33.28	July 1st 2008	<ul style="list-style-type: none">■ Added sub-revision management in Firmup
33.27	Apr 24th 2008	<ul style="list-style-type: none">■ Fixed problem on upgrade FW with some old M4 firmware versions
33.25	Feb 22nd 2008	<ul style="list-style-type: none">■ Fixed bug on M4 Picture Manager
33.23	Feb 4th 2008	<ul style="list-style-type: none">■ Added compatibility with MC4 660
33.19	Dec 12th 2007	<ul style="list-style-type: none">■ Swapped "Upgrade BOOTER" with "Upgrade LANGUAGES"; the Languages will be upgraded immediately after the upgrade of M4■ At the end of FIRMUP " END " will appear (and stay for 10" before Power off with a RED-LED blinking) if the operation is terminated correctly■ When an error occurs, a message ERROR with the code of the error appears■ At the end of "Download Data" or "No New Data" or "Memory Empty", the RED-LED starts blinking for 10" then the M4 is switched off■ Every operation (except the BOOTER upgrade) can be reinitialized, in the bad case of an involuntary interruption (battery, cable, ecc.). Specially the eBOX upgrade can be easily restarted (even if the Firmware is lost)