

## MX2E Release history

Version	Date	Change/additions
<b>02.34.76</b>	Mar, 16th 2022	<ul style="list-style-type: none"><li>▪ Fixed mph speed visualization</li></ul> <b>External modules</b> No changes
<b>02.34.75</b>	Feb, 18th 2022	<ul style="list-style-type: none"><li>▪ Fixed histogram visualization</li><li>▪ Support for 2 video input cameras. Second input needs to be configured from dedicated menu and enabled pressing button on right hand side of the steering column</li><li>▪ Added maximum number for calculated gears</li><li>▪ Fixed unit of measure and label visualization</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>02.36.64</b> GPS09: Improved GPS data synchronization</li><li>▪ <b>02.38.03</b> GPS09B</li></ul>
<b>02.34.66</b>	May, 17th 2021	<ul style="list-style-type: none"><li>▪ Fixed MAF channel factor for 2008-2010 and 2011 onwards model</li><li>▪ Fixed erroneous recording in ROAD mode</li></ul> <b>External modules</b> No changes
<b>02.34.36</b>	Nov, 25th 2020	<ul style="list-style-type: none"><li>▪ Added GPS09 support</li></ul> <b>External modules</b> <ul style="list-style-type: none"><li>▪ <b>35.65</b> GPS Module: Fix Masterclock received from master that caused bad values in GPS data timestamp</li></ul>
<b>02.34.07</b>	Oct, 6th 2020	<ul style="list-style-type: none"><li>▪ Fixed HVAC lighting</li><li>▪ Fixed odometer visualization</li><li>▪ Fixed date/time setting</li></ul> <b>External modules</b> No changes

## MX2E Release history

Version	Date	Change/additions
<b>02.32.79</b>	Jul, 9th 2020	<ul style="list-style-type: none"><li>▪ Added possibility to disable OBDII requests (i.e. for external diagnostics, additional devices, valid for 2008-2010 and 2011-2020 models)</li><li>▪ Added LED startup test</li><li>▪ Added use of parameters to enable/disable seatbelt and sidelight buzzer logic Note:<ul style="list-style-type: none"><li>▪ Seatbelt buzzer is ENABLED by default</li><li>▪ Sidelight buzzer is DISABLED by default</li><li>▪ Sidelight buzzer works with fixed tone when sidelights are ON, doors are open and RPM are 0</li><li>▪ Higher priority is given to seatbelt buzzer</li></ul></li><li>▪ Fixed expansion module configuration (i.e. Shift Light Module)</li><li>▪ Enabled 2nd rear camera inputs (input1 for rear camera trigger on 2011-2020 models), pressing illumination control button to cycle through other inputs</li><li>▪ Possibility to remove gear visualization</li></ul> <p><b>External modules</b></p> <p><b>2.30.20</b> Shift Light Module</p>
<b>02.32.66</b>	Apr, 30th 2020	<ul style="list-style-type: none"><li>▪ Fix RPM bar graph in Digital pages</li><li>▪ Fix Gear display in Blue Road Digital page for 2011-2020 configuration</li><li>▪ Fix cruise control icon</li><li>▪ Activate/deactivate airbag icon warning from menu (in case airbag module is not installed)</li><li>▪ NOTE: after firmware update default model configuration will be installed</li></ul> <p><b>External modules</b></p> <p>No changes</p>
<b>02.32.59</b>	Apr, 23rd 2020	<ul style="list-style-type: none"><li>▪ Display can now have additional channels configured using RS3</li><li>▪ Each of the 16 possible configuration pages can have between 2 and 4 additional fields</li><li>▪ Add TC and TMPS for supported models</li><li>▪ Improved 3 default configurations for all car models</li><li>▪ Fix cruise control icon (for 2011-2020 models)</li></ul> <p><b>External modules</b></p> <p>No changes</p>